

# CIMCO Filter Smoothing the path

## One way filtering

Most filtering software will simply follow the tools path. This can cause problems in zig-zag toolpaths, as the filtering causes the tool to be close to the lower tolerance limit in one direction, and close to the upper tolerance in the other direction. As can be seen in the picture to the left, this causes large scallops, and a poor surface finish.

CIMCO Filter eliminates this problem by detecting the zig-zag nature of the toolpath and performing the filtering calculation in the same direction on all passes. As can be seen in the picture to the right, this gives a much smoother surface. Or you can get the same surface quality as with most other filtering software, with nearly half as many passes.

# Powercut simulation

CIMCO Filter is a stand alone program or part of the powercut simulation and verification software enviroment. The illustrations below were generated by Powercut.

_							
1	CIMCO Filter 3.21	- Ikk	e registrer	et DEM	IO version		
	Filenames						
	Input file						
	I						
	Output file						
	0-V						
	– Options Mode:						
	ISO - ARC specifier						
		0.01	0000				
	Tolerance:		0000	_	Min radius		
	Decimals (0 - 9):	3		_	Max radiu		
	Arc specifier:	CR=	:		Min arc cl		
	✓ Insert G17/G18	Insert G17/G18/G19					
	Always insert G0/G1/G2/G3				Force G1		
					🔲 Only fi		
	<b>CIMCO</b> Integration		<u>I</u> nfo		<u>S</u> tandard		

CIMCO Filter

- Reduced machining time
- Reduced wear on tools
- Reduced program size
- Reduced transmission time





# Product HIGHLIGHTS

T CIMCO Filter 3.2	1 - Ikke registreret DEN	10 version		? ×		
Filenames						
	Input file					
Output file	, Output file					
Coptions						
Mode:						
ISO - ARC speci	ISO - ARC specifier					
Tolerance:	0.010000	Min radius:	0.050000			
Decimals (0 - 9):	3	Max radius:	9999.999			
Arc specifier:	CR=	Min arc chord length	0.050000			
☑ Insert G17/G1	<ul> <li>Insert G17/G18/G19</li> <li>Always insert G0/G1/G2/G3</li> <li>Always insert G2/G3 (G02/G03)</li> </ul>		Force G17/G18/G19 before G0:			
🔲 🔲 Always insert (			Force G17 before G0			
🗖 Always insert (			🔲 Only filter X/Y (G17)			
CIMCO Integration	Info	<u>S</u> tandard	dfør	<u>A</u> fslut		

### Replacement of linear moves

CIMCO Filter replaces the linear movements (G1 in ISO code) output from the CAM system with arc moves (G2/G3 in ISO code).

### Machining strategy

The machining strategy applied will affect the possible reduction; If there are no moves restricted to one of the three main planes (G17, G18 and G19), no reduction will occur. One example of a program, that cannot be reduced, is a parallel toolpath, at a 300 angle to the X-axis.

## Match CNC control and accuracy

It is possible to set tolerance, arc type, number of decimals and minimum and maximum arc radii to match the CNC control and the desired accuracy.

### Efficiency

CIMCO Filter improves the efficiency of your old controls, and allows you to fully utilize the 3D arcs and NURBS options on newer controls.

# NC-programs in ISO and Heidenhain

CIMCO Filter reads NC-programs in ISO and Heidenhain format. Lines are converted into lines and arcs in the XY, XZ and YZ planes (G17, G18 and G19 in ISO code).

### Stand alone program or Powercut.

CIMCO Filter is used as a stand-alone program, however, it can be purchased as part of the Powercut software, which gives you rapid and accurate NC program simulation and verification based on solid technology.

#### Reseller

Europa CIMCO A/S Copenhagen Denmark Tel: +45 45 85 60 50 Fax: +45 45 85 60 53 Web www.cimco.com E-mail info@cimco.com

#### CIMCO Americas

CIMCO Americas, LLC 651 S Sutton Road, Suite 276 Streamwood, IL 60107 Tel: +1 704 644 3587 Fax: +1 704 954 0514

